

[4910-13-P]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-11-0182 *****; Directorate Identifier 2007-NM-262-AD]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model

EMB-135ER, -135KE, -135KL, and -135LR Airplanes, and Model EMB-145, -145ER,

-145MR, -145LR, -145XR, -145MP, and -145EP Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Fuel system reassessment, performed according to RBHA-E88/SFAR-88 (Regulamento Brasileiro de Homologacao Aeronautica 88/Special Federal Aviation Regulation No. 88), requires the inclusion of new maintenance tasks in the Critical Design Configuration Control Limitations (CDCCL) and in the Fuel System Limitations (FSL), necessary to preclude ignition sources in the fuel system. * * *

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by [insert date 30 days after date of publication in the FEDERAL REGISTER].

CONCURRENCES	ADT
ROUTING SYMBOL	ANM116 SR(2)
INITIALS/SIGNATURE	
DATE	11/16/07
ROUTING SYMBOL	Hollyburn 11647
INITIALS/SIGNATURE	HJ
DATE	11/19/07
ROUTING SYMBOL	HAAG
INITIALS/SIGNATURE	TAN
DATE	11/21/07
ROUTING SYMBOL	CT
INITIALS/SIGNATURE	CA
DATE	11/22/08
ROUTING SYMBOL	114
INITIALS/SIGNATURE	RD
DATE	2/12/08
ROUTING SYMBOL	101
INITIALS/SIGNATURE	
DATE	
ROUTING SYMBOL	100
INITIALS/SIGNATURE	FB
DATE	2/13/08
ROUTING SYMBOL	
INITIALS/SIGNATURE	
DATE	